

Issues Register



DOCUMENT: ESD-08-03 Placement of Yard Limit Boards

Note: Issues registers should be checked regularly. When applying the content of a document, users should consider the items in the corresponding register and whether they are appropriate for the given circumstance.

VERSION: 1.0

To report an issue or for more information, please email standards@artc.com.au.

RELATED DOCUMENTS:

Reference	Document Name	Document Type	Date Issued	Status	Comments
1					
2					
3					

CURRENT ISSUES:

Reference	Issue Description	Date Reported	Reported By	Action Required	Action By	Proposed Resolution	Comments/Action Taken to Date	Final Resolution	Status
1	ESD-08-03 in section 3.6. The image depicts two yards limits in close proximity to one another that each uses the same signal with back to back boards. The board allocation (A or B location) is not sufficiently clear (board details are too small).	15/04/2015	I Maydew	Minor Review	Standards	Update image within section 3.6 as shown in following column.			In Progress
2	ESD-08-03 in section 1.4 'Reference Documents' requires a reference to ESD-08-01 - 'Train Order Working'.	15/04/2015	I Maydew	Minor Review	Standards	Update section 1.4 to include a reference to ESD-08-01.	Next revision of ESD-08-03 to update section 1.4 to include reference to ESD-08-01.		In Progress
3									
4									
5									
6									
7									
8									
9									
10									